

# ANNUAL SURVEYS.

19235.

No. Supp 3 Survey held at London Date Sept 8<sup>th</sup> 1854  
 on the Ship "Gorse" Master Redpath  
 Tonnage 940 Built at Sunderland When built 1834  
 By whom built 865 Owners Allan  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Mr's Nigrans Dry Dock

Last Survey, No. 5353 Port of Sunderland Classed 13 A. 1.  
 8,54

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good where seen</u>	Windlass and Capstan	} <u>Good and sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	<u>Yellow Metal</u>	When put on <u>now new</u>	Standing & Running Rigging		
Plank (Bottom) and Counter	<u>Copper Felt partly</u>				

General Observations and Opinion, Now done, the bottom sheathed with yellow metal on Felt the upper course, from thence down on the bare bottom -  
she appears in good and efficient condition eligible  
to remain as classed A. 1. B. W. Maymouth

Committee's Minute 15<sup>th</sup> Sept 1854

Character assigned 13 A. 1 1 Sept 1854

Certificate (if required)

No. Supp 9 Survey held at London Date Sept 8<sup>th</sup> 1854  
 on the Barque "Tiberias" Master Todd  
 Tonnage 485 Built at Sunderland When built 1834  
 By whom built 539 Owners Courley  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Mr's Gowsons Dry Dock

Last Survey, No. 5352 Port of Sunderland Classed 9 A. 1  
 8,54

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good where seen</u>	Windlass and Capstan	} <u>Good and sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	<u>Yellow Metal</u>	When put on <u>now new</u>	Standing & Running Rigging		
Plank (Bottom) and Counter	<u>Copper on Felt</u>				

General Observations and Opinion, Now done, Yellow Metalled on Felt - She appears  
in good and efficient condition, eligible to remain classed  
A. 1.

Committee's Minute 15<sup>th</sup> Sept 1854

Character assigned 9 A. 1 1 Sept 1854

Certificate (if required)