

ANNUAL SURVEYS.

19304

No. 167 Survey held at London Date September 22nd 1854
 on the "African" Master Franklin
 Tonnage 174 Built at Shoreham When built 1836
 By whom built 164 Owners J. Brown
 Port belonging to Bathurst. Rio de Janeiro Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock West India Import Dock

Last Survey, No. 18671 Port of London

Classed 11 S.S. 52
C 4 53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3.1.2.</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. Metal</u> When put on <u>1852</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, This vessel is in a good and efficient state of repair, fit for the safe conveyance of dry and perishable cargo to and from all parts of the world, and eligible, in our opinion, to remain as classed.

Richard Stethell

Committee's Minute 17th Octr 1854

Character assigned E. 1 asterisk

Certificate (if required)

No. 854 Survey held at London Date Sep 27th 1854
 on the Ship "Crystal Palace" Master Linton
 Tonnage 480 Built at Leighmouth When built 1852
 By whom built 494 Owners Lidgett
 Port belonging to London Destined Voyage Hobart Town
 If Surveyed Afloat or in Dry Dock Lincolin dry dock

Last Survey, No. 10409 Port of London

Classed 11 A. 1.
58

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales <u>Caulked</u>	Copper <u>Yellow Metal on Felt</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, now done, Yellow Metal stripped off the bottom Caulked and Wales, bottom resheathed with Yellow Metal on Felt the upper course and from thence to the keel on paper - She now appears in good condition

Committee's Minute 17th Octr 1854 and in my opinion eligible to remain

Character assigned 11A 1 classed A. 1.

Certificate (if required)