

## ANNUAL SURVEYS.

19304

No. 167 Survey held at London Date September 22<sup>nd</sup> 1854  
 on the "African" Master Franklin  
 Tonnage 174 Built at Shoreham When built 1836  
 By whom built 164 Owners J. Brown  
 Port belonging to Bathurst. Rio? Lambra Destined Voyage Africa  
 If Surveyed Afloat or in Dry Dock West India Import Dock

Last Survey, No. 18671 Port of LondonClassed 11 S.S. 52  
C 4 53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <u>3.1.2.</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. Metal</u> When put on <u>1852</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, This vessel is in a good and efficient state of repair, fit for the safe conveyance of dry and perishable cargo to and from all parts of the world, and eligible, in our opinion, to remain as classed.

Committee's Minute 17<sup>th</sup> Octr 1854Character assigned E. 1 asterisk

Certificate (if required)

No. 854 Survey held at London Date Sep 27<sup>th</sup> 1854  
 on the Ship "Crystal Palace" Master Linton  
 Tonnage 480 Built at Leighmouth When built 1852  
 By whom built 494 Owners Lidgett  
 Port belonging to London Destined Voyage Hobart Town  
 If Surveyed Afloat or in Dry Dock Lincolin dry dock

Last Survey, No. 10409 Port of LondonClassed 11 A. 1.  
58

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales <u>Caulked</u>	Copper <u>Yellow Metal on Felt</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, now done, yellow metal stripped off the bottom caulked and wales, bottom resheathed with yellow metal on felt the upper course and from thence to the keel on paper - she now appears in good condition

Committee's Minute 17<sup>th</sup> Octr 1854 and in my opinion eligible to remainCharacter assigned 11A

Certificate (if required)