

No. 698
on the

Survey held at

London

Date

Oct 19

1854

19000

Master

P Caroline

Tonnage

559
394

Built at

N Sco

When built

1852

By whom built

Owners

Hyde & Co

Port belonging to

London

Destined Voyage

Honduras

If Surveyed Afloat or in Dry Dock

In Nelson Dry Dock

Last Survey, No.

18651

Port of

London

Classed

4 A 1

53

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on 1853

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Now done. Dock^d to Scrape the Zinc Sheathing (Belgian) which was thickly covered with Barnacles.

She now appears in good condition eligible to remain as

Committee's Minute

23rd Nov

1854

Character assigned

4 A 1

J. A. Martin

Certificate (if required)