

# ANNUAL SURVEYS.

19485

No. 408 Survey held at London Date Dec<sup>r</sup> 19<sup>th</sup> to 30<sup>th</sup> 1854  
 on the Ship "Hope" Master Dewar  
 Tonnage 747 Built at Miramichi When built 1837  
 By whom built 878 Owners J. Lidger  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Sup<sup>r</sup> Carter's Dry Dock

Last Survey, No. 18486 Port of London Classed 7 A. 1.  
 53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter	Copper on Felt	

Good where seen

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

Now done, the Yellow Metal renewed on Felt, the bottom Caulked, and a deck laid of 3" spruce on the 2<sup>d</sup> Deck beams - She now appears in good and efficient fit in my opinion to remain as classed A. 1.

Committee's Minute 23<sup>rd</sup> January 1855

P. Maymounth

Character assigned

7 A. 1

Certificate (if required)

No. 529 Survey held at London Date Jan<sup>y</sup> 3<sup>rd</sup> 1855  
 on the Barque "Clio" Master Evans  
 Tonnage 357 Built at Sunderland When built 1845  
 By whom built 385 Owners Colling & Co  
 Port belonging to London Destined Voyage Demerara  
 If Surveyed Afloat or in Dry Dock Limokila Slip

Last Survey, No. 19107 Port of London Classed 12 A. 1.  
 6

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper on Felt	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1850</u>	

Good where seen

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways Good

At the present time, laid on the Slip to sight her bottom. - She appears in good condition, fit in my opinion to remain as classed A. 1.

Committee's Minute 23<sup>rd</sup> January 1855

P. Maymounth

Character assigned

12 A. 1

Certificate (if required)