

REPORT of SURVEY for REPAIRS.

19607

J

Re-entry of Class

No. 225 Survey held at London Date Dec^r 1st 1854
 on the Schooner "Catherine" Master E. Williams
 Tonnage 105 Built at Troon When built 1846
 By whom built _____ Owners Hall & Co
 Port belonging to Gloucester Destined Voyage _____
 If Surveyed Afloat or in Dry Dock West India Import Dock (afloat)
O. E. & B.

Last Survey, No. 575 Port Gloucester Classed 5 K. 1 *Clas*
32 *omitted*

REPAIRS

On examination found her in good Condition excepting her ceiling, which has now been repaired.

Present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan <u>which Good</u>
Waterways <u>"</u>	Breasthooks and Stemson _____	Pumps <u>Good</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats <u>One Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good when</u>	Masts, Yards, &c. <u>Good & suff^t</u>
Lower Deck Beams & Fastenings <u>None</u>	Keelsons <u>seen</u>	Sails <u>1 1/2 Suits</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>2 B. 1 S. 1 K</u>
Sheerstrakes <u>Good when</u>	Ceiling <u>repaired</u>	Cables <u>Good and suff^t</u>
Topsides <u>seen</u>	Rudder <u>Line</u>	Hawsers and Warps <u>a a a</u>
Wales _____	Copper _____	Standing & Running Rigging <u>Good & suff^t</u>
Plank (Bottom) and Counter _____	When put on <u>Aug^r 1852</u>	

General Observations and Opinion, *She now appears in good Condition, fit for the conveyance of dry and perishable Cargoes, and in my opinion eligible to be re-entered K. 1.* *M. Weymouth*

The Amount of Fee.....£ 10 : — is received by me,

Special..... : :

Certificate (if required) : 2:6

Committee's Minute 20th April 1855

Character assigned K. 1



© 2019

Lloyd's Register
Foundation

LON 635-0 496