

REPORT of SURVEY for REPAIRS.

No. 158 Survey held at London Date 25 May 1855
 on the Ship "Wigrams" Master J B Thurtell

Tonnage 286 Built at Moulmein When built 1843

By whom built _____ Owners Denny & Co

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock in Messrs Green's Upper Dock.

Last Survey, No. 11449 Port Liverpool Classed 12 A 1

REPAIRS at present from damage bottom stripped
of the wood & yellow metal sheathing hung
in shores and bottom caulked new gaffer
and fore piece of false keel fitted - the
bottom plank from tight water mark dished
bright and examined - the bottom sheathed
with such pine boards on felt and resheathed
with yellow metal - and for continuation
all the outside planks scraped from the light
water mark up and bolts driven out for survey
and all the requirements of Rules 54 Complied

Present Condition of the	<u>Leak Good</u>	Treenails	<u>None</u>	Windlass and Capstan	<u>Good</u>
Decks	<u>Do</u>	Breasthooks and Stemson		Pumps	<u>Do</u>
Waterways	<u>Do</u>	Transoms, Pointers, and Crutches		Boats	<u>Do</u>
Comings	<u>Do</u>	Timbers of the Frame		Masts, Yards, &c.	<u>Do</u>
Upper Deck Beams & Fastenings	<u>few</u>	Keelsons		Sails	<u>Sufficient</u>
Lower Deck Beams & Fastenings	<u>few</u>	Clamps and Shelves	<u>Good</u>	Anchors No. of	<u>Do</u>
Planksheers	<u>Scraped</u>	Ceiling		Cables	<u>Do</u>
Sheerstrakes	<u>bright</u>	Rudder	<u>on wood & felt</u>	Hawsers and Warps	<u>Do</u>
Topsides	<u>Do</u>	Copper	<u>When put on May 1855</u>	Standing & Running Rigging	<u>Do</u>
Wales	<u>Good</u>	Caulking of Bottom, Deck, & Waterways			
Plank (Bottom) and Counter					

General Observations and Opinion,

This vessel is in efficient Condition
and in our opinion eligible to be Continued
on the first Class for the period prescribed

The Amount of Fee £ 3 : - : - is received by me, by the Rules say
Special..... 3 : 3 : - 4 yrs A 1 from 1855
Certificate (if required) : 5 : - J A Ritchie

Committee's Minute 8th June 1855

Character assigned Cont B 1 for 4 yrs

Special Damage £ 3. 3



Lloyd's Register
Foundation

19713 Jan

The upper deck & Comings the upper and
lower deck botts and the outside & Ceiling
Planks the plank sheers waterways and
beams, the house timbers, Knight heads,
and transoms, the floors, & Kellses, the Keel
and Rudder, and the frame & inner surface
of the outside Planks where seen are sound
and good and the general form & sheer
appear unaltered —

J. H. Ritchie



© 2019

Lloyd's Register
Foundation