

# ANNUAL SURVEYS.

19898

No. 19898 Survey held at London Date Aug 15 1855  
 on the Ship Excelsior Master A Jones  
 Tonnage 271 Built at Middlesbrough When built 1855  
 By whom built Holmes & Sons Owners Holmes & Sons  
 Port belonging to Middlesbrough Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock In Mess Somers Dry Dock

Last Survey, No. 1536 Port of Stockton Classed GA 1  
8

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion, Much Cargo in Hold  
now done. The Bottom sheathed with Yellow Metal  
on Telt.

Committee's Minute 11th September 1855  
 Character assigned GA 1 recd J. A. Martin  
 Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 185 \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Committee's Minute \_\_\_\_\_ 185 \_\_\_\_\_  
 Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
 Foundation  
 Certificate (if required)