

REPORT of SURVEY for REPAIRS.

Change of owners

No. 20003 Survey held at London Date Feb^y 23rd 1856
 on the Schooner "Marchioness of Bute" Master _____
 Tonnage 196 Built at Newport When built 1839
 By whom built _____ Owners S. Saunders
 Port belonging to Poole Destined Voyage _____
 If Surveyed Afloat or in Dry Dock London Dec 18

Last Survey, No. _____ Port _____ Classed A, 1.

REPAIRS

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Budder	Hawsers and Warps
Wales	<u>Yellow metal</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> When put on <u>1832</u>	

Good where seen *Good and sufficient*

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good

She is fit for the conveyance of dry and perishable Cargoes, and eligible in my opinion to remain as classed A.
P. Weymouth

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute _____ 185 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON636 - 0301