

REPORT of SURVEY for REPAIRS.

20172

No. 158 Survey held at London Date Feby 11th 185 6
 on the Ship "Nile" Master Sinclair
 Tonnage 658 Built at Sunderland When built 1849
 By whom built _____ Owners D. Dunbar
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock In Miss Somes dry dock and afloat

Last Survey, No. 18417 Port London Classed 13 A 1

REPAIRS

Now done; the yellow metal sheathing stripped off, the ship hung in shrou and recaulked throughout, the Channels renewed and the Chain plates and Bolts also renewed, several additional yellow metal through bolts driven in the upper courses on both sides in the wake of the Foremast and the ship resheathed with Gel. Metal upon Belt. Added one pair of Iron straps to the under side of the lower and one pair to the under side of the upper deck beams bolted to each bow and crossing 4 Beams.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>J. Ma. Feb</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

Good

Good

where seen

In good order

and

sufficient

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good and Sufficient

This Vessel appears to be in a good and efficient state of repair and is eligible in my opinion to remain classed

13 A 1

The Amount of Fee.....£ : : is received by me, Thos. M. Wain

Special..... : :

Certificate (if required) : :

Committee's Minute 22nd February 185 6

Character assigned 1 for 13 Yrs



© 2019

Lloyd's Register Foundation
 LON 636-0467