

20186

REPORT of SURVEY for ~~REPAIRS~~

No. 26 Survey held at London Date 14 February 14 185 6
on the Schooner "Clina" Master Chas. Fregarthen

Tonnage $\frac{120}{83}$ Built at Symington When built 1838

By whom built _____ Owners Dusart

Port belonging to Sally Destined Voyage South America

If Surveyed Afloat or in Dry Dock *Afloat. Victoria & London Rocks*

Last Survey, No. 19279 Port London Classed c 19 ^米AE
8852 34

REPAIRS

Present Condition of the

Decks	} <i>Good</i>	Treenails	} <i>Good</i>	Windlass and Capstan	} <i>In good order</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings	} <i>do</i>	Transoms, Pointers, and Crutches	} <i>where seen</i>	Boats	} <i>and</i>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <i>where seen</i>	Keelsons	} <i>Sufficient</i>	Sails	} <i>Sufficient</i>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} <i>do</i>	Ceiling	} <i>do</i>	Cables	} <i>do</i>
Topsides		Rudder		Hawsers and Warps	
Wales	} <i>do</i>	Copper <i>Y/M on 1st</i> When put on <i>1852</i>	} <i>do</i>	Standing & Running Rigging	} <i>do</i>
Plank (Bottom) and Counter					

General Observations and Opinion.

Caulking of Bottom, Deck, & Waterways. Good and Firm

This vessel appears to be in a good and efficient state of Repair, "fit for the conveyance of dry and perishable cargoes to and from all parts of the world," and is eligible, in our opinion, to remain

The Amount of Fee.....£ — : 10 : — is received by me,

Special..... —————:—————:

Certificate (if required) : 2 : 6

Committee's Minute 4th March 1856

Character assigned *Di. 1 asterisk*

closed 米全

Thos. M^r. Wain

Richard Bethell.

Brokers Baston & Co
Lambourn Chambers, Fenchurch street or Leach & Co.

© 2019

Lloyd's Register
Foundation

WNY636-0481