

# REPORT of SURVEY for ~~REPAIRS~~

and Change of Owners

20227

Recd 20th March

No. <sup>634</sup> ✓ Survey held at London Date 13<sup>th</sup> March 1856  
 on the Barque "Columbus" Master C. W. Hayes  
 Tonnage 467 Built at Whitby When built 1832  
 By whom built \_\_\_\_\_ Owners Armstrong & others  
 Port belonging to Hull Destined Voyage Cardiff & Constantinople  
 If Surveyed Afloat or in Dry Dock Afloat W. St. Expt Dock  
 Last Survey, No. 3227 Port Clyde Classed 11 \* AE 1  
C 4 88 53. 53

REPAIRS

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>G.M.</u> When put on <u>1853</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

firm where seen  
 This vessel is in a good and efficient state and  
 is eligible in my opinion to remain classed \* AE 1

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... : : —

Certificate (if required) : : —

Committee's Minute 28<sup>th</sup> March 1856

Character assigned R. 1 asterisk

Brokers, Ballard & King  
 39 St. Peter Street.



© 2019

Lloyd's Register  
 Foundation

Lon636-0519