

# ANNUAL SURVEYS. 20268

No. 329 Survey held at London Date 1<sup>st</sup> April 1856  
 on the Prince Arthur B.K. Master R. Royal  
 Tonnage 411 Built at Northfleet When built 1854  
 By whom built \_\_\_\_\_ Owners Hud. Bay Comp.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Mess<sup>rs</sup> Somes Dry Dock

Last Survey, No. 19709 Port of London Classed 13 A1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

*This vessel is in good and efficient condition and in my opinion eligible to remain as Classed*

Committee's Minute 18<sup>th</sup> April 1856

Character assigned 13 A1

13 A1.

H. Boulds

Certificate (if required)

No. 8 Survey held at London Date 10<sup>th</sup> March 1856  
 on the B.K. Mallard Master Hill to 14<sup>th</sup> April  
 Tonnage 455 Built at Newcastle When built 1852  
 By whom built 479 Owners Smith & Co  
 Port belonging to Newcastle Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Mess<sup>rs</sup> Wigram's Dry Dock

Last Survey, No. 19446 Port of London Classed 14 A1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways

*Now done - Yellow Metal sheathing patched a new main and Fore mast, and one new Iron Pump. She is in good and efficient condition and in my opinion eligible to remain as Classed*

Committee's Minute 18<sup>th</sup> April 1856

Character assigned 14 A1

Thos McManus

H. Boulds

Certificate (if required)