

# REPORT of SURVEY for REPAIRS.

20271

No. 575 Survey held at London Date 8<sup>th</sup> to 15<sup>th</sup> April 1856  
 on the "Spheroid" Brig Master R. Spragge  
 Tonnage 270 Built at Bermuda When built 1826  
 By whom built \_\_\_\_\_ Owners Scrutton & Co.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Messrs Young's Dry Dock

Last Survey, No. 18717 Port London Classed \*g A. 1. SS. 34

REPAIRS now done.. Yellow Metal Sheathing stripped off, and renewed, Ship hung in Shores and Caulked from Keel to Wale.

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

*good where seen*  
*good*  
*good & sufficient*  
*good*  
*2 good suits*  
*3 B. 1 S. 2 R.*  
*good & sufficient*  
*good*  
*good where seen*  
*now done*

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. *good where seen*

*we are of opinion that this vessel is in good and efficient condition, and "fit for the safe conveyance of dry and perishable Cargoes to and from all parts of the World", and eligible to remain as Classed*

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 22<sup>nd</sup> April 1856

Character assigned A. 1 asterisk

\* A. 1.

H. Boulds

Thos. H. Wain