

20455

REPORT of SURVEY for REPAIRS.

No. 364 Survey held at London Date 23rd June 1856
 on the Bk "Cleopatra" Master Millard
 Tonnage 331 Built at Sunderland When built 1837
368 By whom built _____ Owners Colling & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Limetkin dry Dock

Last Survey, No. 20137 Port London Classed 1/11 A. 1. S.S. 54

REPAIRS now done. — Comings to main Watchway, and one iron breast hook renewed, a new upper Deck of 3 inch yellow pine. Yellow Metal sheathing stripped off and renewed on Pett, vessel hung in shores and caulked from keel to copper line.

Present Condition of the

Decks <u>Upper New</u>	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>good</u>	Keelsons _____	Sails <u>good & sufficient</u>
Planksheers <u>where</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>3 B. 15. 2k</u>
Sheerstrakes <u>seen</u>	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>Y. M.</u> When put on <u>now done</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion, _____
 Caulking of Bottom, Deck, & Waterways. good where seen

"This vessel is now in good and efficient condition, fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world," and in our opinion eligible to remain as Classed 1/11 A. 1.

The Amount of Fee.....£ / : : is received by me,

Special..... : : :

Certificate (if required) : 3 :

Committee's Minute 22nd July 1856

Character assigned F. 1 Asterisk

H. J. Boulds.

Thos W. Wain



Lloyd's Register
Foundation

LOW 634-0165