

ANNUAL SURVEYS.

20512

No. 857 Survey held at London Date June 25th 1856
 on the Schooner "Express" Master John Corsato
 Tonnage 134 Built at Poole When built 1847
 By whom built _____ Owners Nicoll
 Port belonging to Jersey Destined Voyage Newfoundland
 If Surveyed Afloat or in Dry Dock Lavender Dry Dock

Sur. 14 Aug 1856

Last Survey, No. 12479 Port of Liverpool Classed 12 A. 1
 54

The present Condition of the

Decks <u>Good</u>	Treenails _____	Windlass and Capstan _____
Waterways <u>"</u>	Breasthooks and Stemson _____	Pumps _____
Comings <u>"</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>Good and suff.</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes <u>Good</u>	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>Paper</u> When put on <u>now</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>Caul Red</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways Good

Now done, the Copper sheathing renewed on paper the bottom Caul Red and two pairs of iron hanging knees added to the Hold Beams. She is now fit in my opinion to remain as classed 12 A. 1.

B. Weymouth
 Wm Davidson

Committee's Minute 15th August 1856

Character assigned 12 A. 1
Record Yell

Certificate (if required)

No. 348 Survey held at London Date July 18th 1856
 on the Ship "Severn" Master Scowcroft
 Tonnage 475 Built at Scarbro' When built 1847
 By whom built 536 Owners Lindall
 Port belonging to Scarbro' Destined Voyage Portland Bay
 If Surveyed Afloat or in Dry Dock Shorro's Dry Dock

Last Survey, No. 19190 Port of Rondor Classed 13 A. 1
 54

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>Good and suff.</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder <u>Metal</u>	Hawsers and Warps _____
Wales _____	Copper _____ When put on <u>1833</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways Good

Now done, the Metal sheathing patched, and the lower deck Caul Red. She is now fit in our opinion to remain as classed 13 A. 1.

B. Weymouth
 Wm Davidson

Committee's Minute 15th August 1856

Character assigned 13 A. 1
Record Yell

Certificate (if required)