

ANNUAL SURVEYS.

20657

Recd 20th Oct 56

No. 23 Survey held at London Date Oct^r 13th 1856
 on the Barque "Leonidas" Master Allen
 Tonnage 320 Built at Peterhead When built 1854
 By whom built 226 Owners Morrison & Co
 Port belonging to Peterhead Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Messrs Billings Patent Slip

Last Survey, No. 1400 Port of Aberdeen Classed Y A 1 54.

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	<u>In</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame	<u>Good</u>	Masts, Yards, &c.	<u>good order</u>
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons	<u>where</u>	Sails	<u>and</u>
Planksheers	<u>seen</u>	Clamps and Shelves	<u>seen</u>	Anchors No. of	<u>sufficient</u>
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Vales		<u>Y. M.</u>		Standing & Running Rigging	
Plank (Bottom) and Counter		<u>Copper on Felt</u> When put on <u>now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

Now done:- Yellow Metal Sheathing stripped off, and renewed on Felt; Vessel caulked from keel to Metal Line. - Base keel renewed with American Elm. - This Vessel is now in a good state of repair, and is eligible in our opinion, to remain as classed Y A 1.

Committee's Minute 28th October 1856

Character assigned

Y A 1 record Y M L L

H. Boulds
W. Boulds
 Certificate (if Required)

No. 34 Survey held at London Date Oct^r 15th 1856
 on the Barque "Alexandrina" Master Jas. Mason
 Tonnage 294 Built at Aberdeen When built 1848
 By whom built 251 Owners Falconer & Co
 Port belonging to London Destined Voyage Algoa Bay
 If Surveyed Afloat or in Dry Dock afloat in Bermilage Basin, London Docks

Last Survey, No. 19950 Port of London Classed 9 A 1 55.

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	<u>In</u>
Upper Deck Beams & Fastenings		Timbers of the Frame	<u>Good</u>	Masts, Yards, &c.	<u>good order</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Keelsons	<u>where</u>	Sails	<u>and</u>
Planksheers	<u>where</u>	Clamps and Shelves	<u>seen</u>	Anchors No. of	<u>sufficient</u>
Sheerstrakes	<u>seen</u>	Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Vales		<u>Y. M.</u>		Standing & Running Rigging	
Plank (Bottom) and Counter		<u>Copper on Felt</u> When put on <u>1855</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This Vessel is in a good state of repair, and is eligible, in our opinion to remain as classed 9 A 1.

Committee's Minute 28th October 1856

Character assigned

9 A 1 L L

H. Boulds
W. Boulds
 Certificate (if Required)

Register
 Foundation

LON637-0346