

ANNUAL SURVEYS.

20869

No. 218 on the *Ship "Northfleet"* Survey held at *London* Date *Jan^y 30th to Feb^y 3rd 1857*
 Master *Robert Freeman*
 Tonnage *195* Built at *Northfleet* When built *1853*
 By whom built *W. D. Dunbar* Owners *W. D. Dunbar*
 Port belonging to *London* Destined Voyage *China*
 If Surveyed Afloat or in Dry Dock *in Messrs Carters dry Dock*

Last Survey, No. *19596* Port of *London* Classed *14A 1*
 1156

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. The metal sheathing stripped off the bottom and two pairs of long iron diagonal plates 8 x 1 1/2 in fitted in the fore hold through bolted with 7/8 Copper. The vessel caulked from the keel to the metal line and the bottom sheathed with yellow metal on felt. She is in good condition and in our opinion eligible to remain as classed 14A 1

Committee's Minute *17th February 1857*

Character assigned

*14A 1**record M D*

Certificate (if required)

No. 932 on the *Ship "Cumberland"* Survey held at *London* Date *28th Jan^y to Feb^y 12th 1857*
 Master *Duncan*
 Tonnage *931* Built at *Sunderland* When built *1856*
 By whom built *Graham* Owners *Graham*
 Port belonging to *Newcastle* Destined Voyage *Calcutta*
 If Surveyed Afloat or in Dry Dock *in Lincolns dry dock & London Dock*

Last Survey, No. *5750* Port of *Sunderland* Classed *13A 1*
 1156

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. The metal sheathing dressed, and the vessel caulked from the metal line to the third seam of deck inside of waterway, also the poop and fore-castle drifts. She is in good condition and in our opinion eligible to remain as classed 13A 1

Committee's Minute *17th February 1857*

Character assigned

*13A 1**record M D*

Certificate (if required)