

REPORT of SURVEY for REPAIRS.

No. 21088 Survey held at London Date June 5th 1857
 on the Ship "Her Majesty" Master J. L. Dennes
 Tonnage 1112 Built at Calcutta When built 1856
 By whom built _____ Owners E. Fox & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock East India dock

Last Survey, No. _____ Port _____ Classed 12 A.

REPAIRS

The following stores have now been supplied, one Bower anchor of 45 cwt. and 90 fathoms of $1\frac{1}{8}$ Chain also a stream chain ^{faths} 60 and one warp of $6\frac{1}{2}$ lbs to complete her.

Present Condition of the

| | | |
|---|--|---|
| Decks <u>good</u> | Treenails _____ | Windlass and Capstan <u>good</u> |
| Waterways <u>"</u> | Breasthooks and Stenson _____ | Pumps <u>"</u> |
| Comings <u>"</u> | Transoms, Pointers, and Crutches <u>good</u> | Boats <u>3 good</u> |
| Upper Deck Beams & Fastenings <u>good</u> | Timbers of the Frame <u>where seen</u> | Masts, Yards, &c. <u>good & sufficient except the main top sail</u> |
| Lower Deck Beams & Fastenings <u>where seen</u> | Keelsons <u>seen</u> | Sails <u>good</u> |
| Planksheers <u>"</u> | Clamps and Shelves _____ | Anchors No. of <u>3 B. 13. 116.</u> |
| Sheerstrakes <u>"</u> | Ceiling _____ | Cables <u>good and sufficient</u> |
| Topsides <u>"</u> | Rudder _____ | Hawsers and Warps <u>good</u> |
| Wales <u>"</u> | Copper <u>seen</u> When put on <u>1857</u> | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter <u>"</u> | | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now complete in her stores except the main top sail yard which by the letter attached shews to be forth coming; I am of opinion she is eligible to be classed 12 A.

The Amount of Fee.....£ : : is received by me, J. T. Light
 Special..... : :
 Certificate (if required) : :

Committee's Minute _____ 185_____

Character assigned _____



© 2019

Lloyd's Register Foundation

LON 638-0285