

ANNUAL SURVEYS.

21186
H. J. B. v. L. R.

No. 301 Survey held at Bydon Date 11th July 1857
 on the Ship "Bombay" Master Blamant
 Tonnage 1200 Built at Bombay When built 1809
 By whom built 1297 Owners C. S. Dunbar
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat off Blackwall and in Somerset Dry Dock.

Last Survey, No. 21121 Port of London Classed 1st F. 1
BC 1854

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson	Pumps <u>New</u>
Comings	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>4 good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>seen</u>	Sails <u>2 good suit</u>
Planksheers <u>Good where seen</u>	Clamps and Shelves	Anchors No. of <u>4 B. 15. 2 k</u>
Sheerstrakes	Ceiling	Cables <u>Good and sufficient</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. M.</u> When put on <u>1854</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This vessel is now in good and efficient condition, fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world and in our opinion eligible to remain as Classed 1st F. 1.

Committee's Minute 21st July 1857

Character assigned L. R. 1

Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Committee's Minute _____ 185____

Character assigned _____



© 2019

Lloyd's Register
 Certificate (if required)
 Foundation