

21236

# REPORT of SURVEY for REPAIRS.

No. 340 on the Steamer Survey held at London Date 10<sup>th</sup> July 1857  
 " Grident Master J. W. Morris  
 Tonnage 902 Built at London When built 1841  
 By whom built 645 Owners G. S. & Co.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock General Steam dry Dock

Recd of 10/17

Last Survey, No. 20391 Port London Classed 12 A1  
 Cont 53 - 4 <sup>56</sup>

## REPAIRS

Now done, in accordance with the Rules Sec<sup>n</sup> 60 for Red A part 1<sup>st</sup>.  
 The vessel placed in dry Dock. Yellow metal sheathing stripped off  
 the bottom, and scraped bright from the light water-mark  
 upwards including the plank sheers and waterways, bolts and  
 treenails driven out for survey.

Repairs viz. 3 forehoods of Topsides on the starboard  
 side, 2 forehoods and one shift of Topsides amidships on the port  
 side all renewed of Red pine. The general state of the frame,  
 treenails, and inside of the planking examined. The bolts  
 and treenails which were driven out renewed. The vessel  
 P. M. O.

## Present Condition of the

|   |   |  |
|---|---|--|
| Decks <u>good</u>                               | Treenails _____                                   | Windlass and Capstan <u>good</u>       |
| Waterways <u>"</u>                              | Breasthooks and Stenson <u>good</u>               | Pumps _____                            |
| Comings <u>"</u>                                | Transoms, Pointers, and Crutches <u>where</u>     | Boats _____                            |
| Upper Deck Beams & Fastenings <u>good</u>       | Timbers of the Frame <u>seen</u>                  | Masts, Yards, &c. <u>good order</u>    |
| Lower Deck Beams & Fastenings <u>where seen</u> | Keelsons <u>good</u>                              | Sails <u>and sufficient</u>            |
| Plank sheers <u>good</u>                        | Clamps and Shelves _____                          | Anchors No. of <u>3 B, 1 S, 2 K.</u>   |
| Sheerstrakes <u>"</u>                           | Ceiling _____                                     | Cables <u>sufficient good</u>          |
| Topsides <u>"</u>                               | Rudder _____                                      | Hawsers and Warps _____                |
| Wales <u>"</u>                                  | Copper <u>Yellow Metal</u> When put on <u>now</u> | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter _____                | <u>on Shell</u>                                   |  |

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. New and good

This vessel has now been specially surveyed in strict accordance  
 with the Rules Sec<sup>n</sup> 60 part 1<sup>st</sup>, and having been thoroughly repaired and  
 made "fit for the safe conveyance of dry and perishable goods to and from  
 all parts of the world" we are of opinion she is now eligible to retain her

The Amount of Fee.....£ 2 : - : is received by me,  
 Special..... 5 : 5 : present character A1 to the end  
 Certificate (if required) : : of this year, and then classed A1 in Red  
 and marked SS - 4 years from 1857

Committee's Minute 18<sup>th</sup> August 1857

Character assigned Contd. till the end of present year  
Extra Special 2.2.0  
P. S. 1857  
 J. S. Pittman  
 Lloyd's Register  
 Foundation  
 LON 638-0425

21236 Lon

hung in shores, caulked throughout, and resheathed with yellow metal on Telt. "The upper or main deck and coverings, the upper and lower deck bolts, and the outside planks through which they pass, the planksheers, waterways, and beams, so far as they can be examined; the hause timbers, knightsheads, breasthooks, and transoms; the floors and keelsons; the keel, rudder, and windlass; the planking outside and inside, and the treenails; and the frame and inner surface of the outside planking where they can be seen appear in good condition and the sheer and general form of the Ship unaltered

J. H. Tiltman



© 2019

Lloyd's Register  
Foundation