

# ANNUAL SURVEYS.

21350

No. 86 Survey held at London Date 24<sup>th</sup> Sept<sup>r</sup> 1854  
 on the Bk "Unies" Master J. H. Hall  
 Tonnage 226 Built at Scarbr<sup>e</sup> When built 1852  
 By whom built 233 Owners Bindall  
 Port belonging to London Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Bindall's Dry Dock and West. I. Dock.

Last Survey, No. 19912 Port of London Classed 12 A. 1.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

*Now done: Yellow metal sheathing stripped off and renewed upon paper. Vessel caulked from the keel to metal line. She is now in good and efficient condition and in my opinion eligible to remain as Classed 12 A. 1.*

Committee's Minute

Character assigned

No. 87 Survey held at London Date 29<sup>th</sup> Sept<sup>r</sup> 1854  
 on the Bk "Arabia" Master C. Jones  
 Tonnage 330 Built at Scarbr<sup>e</sup> When built 1844  
 By whom built 389 Owners P. Bindall  
 Port belonging to London Destined Voyage 99 Cyprus  
 If Surveyed Afloat or in Dry Dock Bindall's Dry Dock.

Last Survey, No. 207611 Port of London Classed 11 A. 1. Con<sup>t</sup> 55

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

*Now done: Yellow metal sheathing patched. Buttocks & part of the topsides and wales aft caulked. She is in good and efficient condition and in my opinion eligible to remain as Classed 11 A. 1.*

Committee's Minute

Character assigned

Certificate (if required)

LON 639-0028