

# REPORT of SURVEY for REPAIRS.

21466

No. 327 Survey held at London Date 10<sup>th</sup> Nov<sup>r</sup> 1857  
 on the Ship "Mars" Master J James  
 Tonnage 721 Built at Sunderland When built 1856  
 By whom built \_\_\_\_\_ Owners J Allen  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Mess<sup>rs</sup> Fletchers dry Dock

Last Survey, No. 5776 Port Sunderland Classed 13 A1

## REPAIRS

of Damage now done, The Yellow Metal sheathing stripped off, the fore piece of Keel repaired by piecing, the ship hung in shores and caulked from keel to metal line, Yellow Metal sheathing renewed on Telt down to the Bilge remainder on paper -

## Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>where</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>seen</u>	Masts, Yards, &c. <u>good order</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>good</u>	Sails <u>and sufficient</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 13. 1 S. 2 K</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>sufficient good</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Y Metal</u> When put on <u>now</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is now in good and efficient condition and eligible in our opinion to remain as classed A1

The Amount of Fee.....£ : : is received by me,

Special..... 4: 4: -

Certificate (if required) : :

Committee's Minute 15<sup>th</sup> December 1857

Character assigned 13 A1



© 2019

Lloyd's Register  
Foundation

LON 639-0139