

21500

REPORT of SURVEY for REPAIRS.

No. 183 Survey held at London Date 29 Feb 1857
on the Ship "Gilmore" Master Scott
Tonnage 500 Built at Calcutta When built 1824
By whom built _____ Owners Bryant & Co. Brigman Owners
Port belonging to London Destined Voyage Bombay
If Surveyed Afloat or in Dry Dock in Mr. Wigram's Dock
cl 41 JMA 55 then 29 w T Sds d 48 D. d 35 Sx p 7 55
Last Survey, No. 20109 Port London Classed *A. 1 Clap on the
SS 1855

Recd 18/12/57
Cmty

REPAIRS

Docked at present to inspect the state of the
yellow metal sheathing which was found
in good order

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Ym</u> When put on <u>1855</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. overhauled at this time

This vessel appeared to be in good & efficient
condition and in my opinion fit for the safe

The Amount of Fee.....£ : :
Special..... : :
Certificate (if required) : :

is received by me,

Conveyance of dry &
Perishable Cargoes
to & from all Ports
of the world & eligible
to remain as Clapped
*A. 1

Committee's Minute 19th February 1858

Character assigned *A. 1 Asterisk

© 2019
Ritchie's Register
Foundation