

ANNUAL SURVEYS.

21649

No. 911 Survey held at London Date 25th Feb^r 1858
 on the Ship "Mountstuart Elphinstone" Master W. H. Sand
 Tonnage 611 Built at Bombay When built 1826
 By whom built J Owners Somes B^r
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Somes Dry Dock and Afloat West India Dock

Last Survey, No. 20547 Port of London Classed * A. 1. S. S. 53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. M.</u> When put on <u>1856</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

This Vessel is now in good Condition, fit for the safe conveyance of dry and perishable cargoes to and from all parts of the World and in my opinion eligible to remain as Classed -

Committee's Minute 6th April 1858 - * A. 1. H. B. Bolds.

Character assigned * 1 asterisk LR

Certificate (if required)

No. 20 Survey held at London Date March 18th 1858
 on the Ship "Canning" Master J. Robertson
 Tonnage 229 Built at Moulmain When built 1854
 By whom built Owners Somes B^r
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Miss^{rs} Somes Dry Dock and Afloat C^t S. Dock

Last Survey, No. 20477 Port of London Classed 15 A. 1. S. S. 56

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. M.</u> When put on <u>1856</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good where seen

Repairs now done viz: - One counter plank renewed of Sheat on each side at the Knuckle. Vessel caulked from the metal line upwards to the planksheer. She is now in good and efficient condition and in our opinion eligible to remain as

Committee's Minute 6th April 1858 - Classed 15 A. 1. H. B. Bolds.

Character assigned 15 A. 1 LR

Certificate (if required)

LON 639-0307