

REPORT of SURVEY for REPAIRS.

21834

Rec 1/6/48

No. 122 Survey held at London Date 31st May 1858
 on the Ship Marchioness of Londonderry Master J Davidson
 Tonnage 809 Built at Newcastle When built 1857
 By whom built _____ Owners Geo Marshall
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Globe Dock

Last Survey, No. 19818 Port London Classed 13 A 1

REPAIRS

Docked at Present to inspect the state of the Yellow Metal Sheathing which was found smooth but wasted at the butts of the sheets and has been stripped off and the butts, hooding ends, and bilges, have been Caulked and the bottom resheathed with yellow metal

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Ym</u> When put on <u>June 1858</u>	Standing & Running Rigging
Plank (Bottom) and Counter	Caulking of Bottom, Deck, & Waterways. <u>good</u>	

This vessel is in good & efficient Condition and fit to remain as Classed

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 2nd July 1858

Character assigned 13 A 1



© 2019

Lloyd's Register Foundation

LN640-0033