

ANNUAL SURVEYS.

21894

No. 480 Survey held at London Date July 15th 1858
 on the Ship "Kiddaw" Master N. B. D. Gardner
 Tonnage 443 Built at Worthington When built 1832
 By whom built 376 Owners Pathbone
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Recd July 1858

Last Survey, No. 19947 Port of London Classed 9 A. 1.
56

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps } <u>Good</u>
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats <u>3 in the fore</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons } <u>Good where seen</u>	Sails <u>2 suits good</u>
Planksheers	Clamps and Shelves } <u>seen</u>	Anchors No. of <u>3 B. 1 S. 1 H.</u>
Sheerstrakes } <u>Good when seen</u>	Ceiling	Cables
Topsides } <u>Good when seen</u>	Rudder	Hawsers and Warps } <u>Good & suff.</u>
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>	Copper on felt } When put on <u>now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>	

Now done, one upper deck beam end renewed, the bottom Caulked and sheathed with Yellow Metal on felt - She appears fit in my opinion to remain as classed

Committee's Minute 30th July 1858 9 A. 1.
 Character assigned 9 A. 1. Record Yell B. Weymouth
 Certificate (if required)

No. 232 Survey held at London Date 17th July 1858
 on the Ship "Loreunner" Master Chas. Gibson
 Tonnage 570 Built at Sunderland When built 1835
 By whom built 558 Owners Hudson
 Port belonging to Sunderland Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Union Dry Dock

Last Survey, No. 21294 Port of London Classed 10 A. 1.
57

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>firm</u>	Keelsons } <u>Good where seen</u>	Sails } <u>Suff.</u>
Planksheers	Clamps and Shelves } <u>seen</u>	Anchors No. of
Sheerstrakes } <u>Good when seen</u>	Ceiling	Cables
Topsides } <u>Good when seen</u>	Rudder	Hawsers and Warps
Wales	Yellow Metal	Standing & Running Rigging
Plank (Bottom) and Counter <u>ft Caulked</u>	Copper } When put on <u>part now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, and Waterways <u>Good</u>	

Now done, the Yellow Metal stripped and renewed from the light to the load line - She is fit in my opinion to remain as classed

Committee's Minute 30th July 1858 10 A. 1. B. Weymouth
 Character assigned 10 A. 1. Record Yell B. Weymouth
 Certificate (if required).