

ANNUAL SURVEYS.

219 111

No.
338Survey held at LondonDate June 16th to July 14th 1858

on the

Ship "Charlotte Jane"

Master

W. Rupel

Tonnage

614

Built at

Bristol

When built

1848

By whom built

W. Patterson

Owners

Messrs Thomson & Co

Port belonging to

London

Destined Voyage

Sup^r Bilbes' Dry Dock

If Surveyed Afloat or in Dry Dock

Last Survey, No.

20761

Port of

London

Classed

13 A. 1.

56

The present Condition of the

Decks

Good

Waterways

Caulked

Comings

Good

Upper Deck Beams & Fastenings

firm

Lower Deck Beams & Fastenings

firm

Planksheers

Caulked

Sheerstrakes

Caulked

Topsides

Caulked

Wales

Caulked

Plank (Bottom) and Counter

Caulked

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Yellow MetalCopper

When put on

1836

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, the Rupel Caulked from the Metal sheathing to the second seam of deck inside the waterways, the waterway seams of the lower deck and poop - the Mizen Mast and four hold stanchions.

Committee's Minute

3rd August 1858

Character assigned

13 A. 1.

Renewed - She is now fit in my opinion to remain as classed.

P. Weyman auth
Certificate (if required)

Charge £1.1.0 Paid 13/8/58

No.
332Survey held at LondonDate July 6th to 7th 1858

on the

Ship "Aurora Australis"

Master

C. Copping

Tonnage

305

Built at

Sunderland

When built

1836

By whom built

W. C. Pherson

Owners

W. C. Pherson

Port belonging to

London

Destined Voyage

Stobart Town

If Surveyed Afloat or in Dry Dock

Union Dry Dock

Last Survey, No.

20749

Port of

London

Classed

13 A. 1.

56

The present Condition of the

Decks

Good

Waterways

Caulked

Comings

Good

Upper Deck Beams & Fastenings

firm

Lower Deck Beams & Fastenings

firm

Planksheers

Caulked

Sheerstrakes

Caulked

Topsides

Caulked

Wales

Caulked

Plank (Bottom) and Counter

Caulked

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Yellow MetalCopper on paper

When put on

now

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done, the Caulking tested, found good; her bottom sheathed with Yellow Metal on Paper - She is now fit in my opinion to remain as classed 13 A. 1.


Committee's Minute

3rd August 1858

Character assigned

13 A. 1.

Charge £1.1.0 Paid 13/8/58



Certificate (if required).

Lloyd's Register

Foundation

LON640-0100