

21963

REPORT of SURVEY for REPAIRS.

2nd time term survey

No. 385 Survey held at London Date 20th & 30th July 1858
on the Barge Guadalete Master Adams R Datchell
Tonnage 331 Built at Wells When built 1854
By whom built 275 Owners Riley & Co
Port belonging to London Destined Voyage London to Vancouver Island
If Surveyed Afloat or in Dry Dock Buck Head Dry Dock

Last Survey, No. 19626 Port London Classed AA1
53

REPAIRS

The yellow metal sheathing stripped, the bottom caulked and resheathed with yellow metal on paper.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>DM - Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>2</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>2</u>
Upper Deck Beams & Fastenings <u>Good where seen</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>Seen</u>	Keelsons <u>Good</u>	Sails <u>2 suits</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 18-15 2 16</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>24 fms 3 main</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>4</u>
Wales <u>"</u>	Copper <u>on paper</u> When put on <u>now done</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. Good where tried
This vessel is in good & efficient condition eligible to remain as classed AA1

The Amount of Fee.....£ : : is received by me, W. W. Wain
Special..... 1 : 1 : 7
Certificate (if required) : 5 : 3

Committee's Minute 10th September 1858
Character assigned AA1

Record of

