

# REPORT of SURVEY for ~~REPAIRS~~ <sup>Stores</sup>

No. 21981 Survey held at London Date 15<sup>th</sup> Sept<sup>r</sup> 1858  
 on the "Priscilla" Master Sturley  
 Tonnage 244 Built at Wells, Norfolk When built 1858  
 By whom built W. S. S. S. Owners Bullard & Co  
 Port belonging to London Destined Voyage   
 If Surveyed Afloat or in Dry Dock In dry dock (Globe) and Afloat

Last Survey, No. 21981 Port London Classed 10 A  
 REPAIRS Not yet done

*Now done, recaulked from keel to metal  
 line and sheathed with Yellow Metal*

*Testing certificates of chains have been  
 examined*

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where seen

*This vessel is now in my opinion  
 eligible to be classed 10 A 1*

The Amount of Fee.....£ : : is received by me,

Special..... 1: 1: :

Certificate (if required) : :

Committee's Minute 17<sup>th</sup> September 1858

Character assigned 10 A 1

*Thos. W. Waver*



© 2019

Lloyd's Register  
 Foundation

LON640-0176