

REPORT of SURVEY for REPAIRS.

No. 18 Survey held at London Date July 15th 1858
 on the Barge "Palestine" Master A. Alexander
 Tonnage 467 Built at Newcastle When built 1834
 By whom built _____ Owners Stephenson & Co
 Port belonging to London Destined Voyage Association
 If Surveyed Afloat or in Dry Dock Swansea Dry Dock

Last Survey, No. 21261 Port London Classed S.S. 1832/10 1
C 3 57

REPAIRS

Now done, Caulked from the Keel to the Gunwale and the upper deck, tested the Caulking which proved satisfactory, the bottom sheathed with Yellow Metal on Sels, two planks of deck near the waterway renewed

Present Condition of the

Decks <u>Caulked</u>	Treenails	Windlass and Capstan
Waterways <u>Caulked</u> } <u>good</u>	Breasthooks and Stemson	Pumps
Comings <u>Caulked</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Good when</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>fine</u>	Keelsons <u>seen</u>	Sails <u>Good and</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides <u>Caulked</u>	Rudder <u>Y. Metal on</u>	Hawsers and Warps
Wales	Copper <u>Sels</u> } When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good

She appears to be in good Condition, fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world, and to remain classed S.S. 1 Asterisk B.

The Amount of Fee.....£ : : is received by me, R. Wymouth

Special..... 1 : 1 : } R.C.

Certificate (if required) : 5 : }

Committee's Minute 1st October 1858

Character assigned A. 1 Asterisk

Charge £ 1. 1. 0 paid R.C.



© 2019

Lloyd's Register Foundation

7810-04907