

REPORT of SURVEY for REPAIRS.

22026

No. 231 on the S. Forester Survey held at London Date 23rd July 1858
 Master Mc Dougal
 Tonnage 370 Built at Chepstow When built 1826
 By whom built _____ Owners Ellice & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Dowson's Ways
pt E & d 56 Siprs 57 & 56 W & T Sds Ed 56
 Last Survey, No. 20615 Port London Classed 11th N. 1
 REPAIRS omitted
ss. 56

Now done one pair of Iron hanging knees added to lower deck beams - and Yellow Metal repaired

Present Condition of the

Decks	Treenails	Windlass and Capstan <u>Winch</u> <u>good</u>
Waterways	Breasthooks and Stemson	Pumps <u>2 & 2 bilge</u> <u>do</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>2</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>good where seen</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons	Sails <u>2 suits</u>
Planksheers	Clamps and Shelves <u>where seen</u>	Anchors No. of <u>3 x 1 x 1</u>
Sheerstrakes <u>where seen</u>	Ceiling	Cables <u>sufficient</u>
Topsides	Rudder	Hawsers and Warps <u>7/2 x 7 x 5</u>
Wales	Copper <u>SM on T</u> When put on <u>1856</u>	Standing & Running Rigging <u>good where seen</u>
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This vessel is now in good condition "fit for the conveyance of dry and perishable cargoes to and from all parts of the world" and is eligible in my opinion to resume her class

11th N. 1

The Amount of Fee.....£ 1 : - : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : : -

Committee's Minute 15th October 1858

Character assigned B. 1 asterisk

Scullion, Port Co



© 2019

Lloyd's Register Foundation

LN640-0213