

REPORT of SURVEY for REPAIRS.

22077

No. 166 Survey held at London Date 21st October 1858
 on the Barque Agnes Master Crawford
 Tonnage 339 Built at Bristol When built 1842
 By whom built _____ Owners Thomson & Co
 Port belonging to London Destined Voyage London to West Indies
 If Surveyed Afloat or in Dry Dock Afloat West-India Docks

Last Survey, No. 21340 Port London Classed 12 A1
Sub 54-D. 37.

REPAIRS

The upper deck now doubled with two inch mangrove bar.

Present Condition of the

Decks <u>Doubled</u> <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson <u>Not seen for Cargo</u>	Pumps <u>2</u>
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>Good where</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>seen</u>	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>318 15 16</u>
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder <u>Good</u>	Hawsers and Warps _____
Wales _____	Copper <u>When put on 1837</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen.

This Vessel had cargo on board at the time the deck was being doubled. She appears in good and efficient condition eligible to remain as classed. A 1

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 7/11

Certificate (if required) : 5 :

Committee's Minute 23rd November 1858

Character assigned Best SE



© 2019

Lloyd's Register
Foundation

LON640-0256