

22155

REPORT of SURVEY for REPAIRS.

No. ✓ Survey held at London Date 13th to 15th Nov^r 1858
 on the new B^k "Sea Nymph" Master C. R. Stoppenheim
 Tonnage 256 Built at Weymouth When built 1838
 By whom built C. Desaut Owners C. Desaut Jun^r Desaut
 Port belonging to London Destined Voyage Vancouver's Island
 If Surveyed Afloat or in Dry Dock new Crane dry dock

Last Survey, No. 997 Port Southampton Classed

REPAIRS

Now done Stowed Beam Clamps through bolter with $\frac{13}{16}$ in
 Yellow Metal and Upper Deck Clamps with $\frac{13}{16}$ in Iron, recaulked
 from keel to upper part of Wales and Yellow Metal on feet to
 Wales -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Budder	Hawsers and Warps
Wales	<u>Yellow Metal on Feet</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper</u> When put on <u>Nov^r 38</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tried

This Vessel appears in good condition and eligi-
 ble in our opinion for the class recommended viz 8 A 1

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 3/1/59

Certificate (if required) : :

Committee's Minute 4th January 1859

Character assigned 8 A 1



© 2019

Lloyd's Register
Foundation

LON640-0335