

# ANNUAL SURVEYS.

22187

Dec 3/2/59

No. 290 Survey held at London Date Dec 22<sup>nd</sup> 5<sup>th</sup> Feb 20. 1853  
 on the Ship Transvaal Master T Brown  
 Tonnage 302 Built at Cochin When built 1840  
 By whom built \_\_\_\_\_ Owners Thomson  
 Port belonging to London Destined Voyage London to Port of Spain  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. 20762 Port of London Classed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>New Main Mast &amp; Bowst.</u>
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails <u>2 Bunt</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>3 B 13 16</u>
Sheerstrakes <u>Caulked</u>	Ceiling <u>of Hold. Not seen on second of Cays</u>	Cables <u>155</u>
Topsides _____	Rudder _____	Hawsers and Warps <u>Sufficient</u>
Wales <u>Good where seen</u>	Copper <u>on Felt</u> When put on <u>1856</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This Vessel is in good and efficient condition eligible to remain as classed 12A1

Committee's Minute 4<sup>th</sup> February 1859

Character assigned 12A1

Certificate (if required)

No. 306 Survey held at London Date 26<sup>th</sup> 27<sup>th</sup> Jan 1859  
 on the Barge "Honey" Master J. Gillies  
 Tonnage 414 Built at Sunderland When built 1850  
 By whom built \_\_\_\_\_ Owners Prosser Bros  
 Port belonging to London Destined Voyage London to Barbadoes  
 If Surveyed Afloat or in Dry Dock Bridge Dock, Royal & London Docks

Last Survey, No. 1207 Port of Sunderland Classed 13A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps <u>On 8 B</u>
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>3</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails <u>2 Bunt</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>8 B 18 16</u>
Sheerstrakes _____	Ceiling _____	Cables <u>Sufficient</u>
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>on Felt</u> When put on <u>1850</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This Vessel is in good & efficient condition eligible to remain as classed 13A1

Committee's Minute 4<sup>th</sup> February 1859

Character assigned 13A1

Certificate (if required)



Lloyd's Register Foundation

LON 640 - 0365