

# ANNUAL SURVEYS.

22274

No. 165 on the Ship "Jane Leck" Master Richardson  
 Tonnage 870 Built at Biddeford When built 1854  
 By whom built Owners J. Leck  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock Fletcher's dry dock

Last Survey, No. 21712 Port of London Classed 13 A 1.  
 58

The present Condition of the

Decks	good	Treenails		Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson		Pumps	"
Comings	"	Transoms, Pointers, and Crutches		Boats	good and efficient
Upper Deck Beams & Fastenings	good	Timbers of the Frame	good	Masts, Yards, &c.	main mast now new.
Lower Deck Beams & Fastenings	where seen	Keelsons	where	Sails	
Planksheers	"	Clamps and Shelves	seen	Anchors No. of	3 B, 1 S, 2 V
Sheerstrakes	"	Ceiling		Cables	good and complete
Topsides	"	Rudder		Hawsers and Warps	
Wales	"	Copper	When put on now done	Standing & Running Rigging	
Plank (Bottom) and Counter	Caulked				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. yellow-metal stripped off the bottom vessel caulked from rail to metal line, also the butt of upper works where found necessary. yellow-metal renewed on felt. - She now appears in good condition

Committee's Minute 8<sup>th</sup> March 1859 and in my opinion eligible to remain as Classed 13 A 1.  
 Character assigned 13 A 1

record W. M. L. J. F. Light Certificate (if required)

No. 25 on the Ship "Maggie Miller" Master P. I. Johns  
 Tonnage 1332 Built at N. Brunswick When built 1855  
 By whom built Owners I.rowse.  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock Young's dry dock.

Last Survey, No. 159 Port of St. John Classed 7 A 1.  
 57

The present Condition of the

Decks	good	Treenails		Windlass and Capstan	good
Waterways	"	Breasthooks and Stemson		Pumps	"
Comings	"	Transoms, Pointers, and Crutches		Boats	good and sufficient
Upper Deck Beams & Fastenings	good	Timbers of the Frame	good	Masts, Yards, &c.	
Lower Deck Beams & Fastenings	where seen	Keelsons	where	Sails	
Planksheers	"	Clamps and Shelves	seen	Anchors No. of	3 B, 1 S, 1 V
Sheerstrakes	Caulked	Ceiling		Cables	good and complete
Topsides	"	Rudder		Hawsers and Warps	
Wales	"	Copper	When put on now done	Standing & Running Rigging	
Plank (Bottom) and Counter	"				

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Now done. yellow-metal stripped off the bottom. vessel caulked from rail to lower part of wood beam topping and from upper part of A. upwards, some of the bolts in pulleys and braces renewed, and metal renewed on felt. - She now appears in good condition and in my opinion eligible to remain as Classed 7 A 1.

Committee's Minute 8<sup>th</sup> March 1859  
 Character assigned 7 A 1

record W. M. L. J. F. Light Certificate (if required)