

ANNUAL SURVEYS.

22288

Recd 9.3.59
Car

No. ¹⁵⁴ Survey held at London Date 4th March 185 9
 on the Steamer Susan Master Colling
 Tonnage 190 Built at Cones When built 1839
 By whom built _____ Owners Colling
 Port belonging to London Destined Voyage London
 If Surveyed Afloat or in Dry Dock West's Quay

Last Survey, No. 21400 Port of London Classed 12 A 1
Ent 56. 7. 57

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps <u>2</u>
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>2</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons <u>Cones with Ballast</u>	Sails <u>2 suits</u>
Planksheers _____	Clamps and Shelves <u>Good where seen</u>	Anchors No. of <u>3 B. 1 S. 1 H.</u>
Sheerstrakes <u>Good where seen</u>	Ceiling <u>gal covered</u>	Cables <u>sufficient</u>
Topsides _____	Rudder <u>Good</u>	Hawsers and Warps _____
Wales _____	Copper <u>Iron</u> When put on <u>1856</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This vessel appears in good and efficient condition eligible to remain as classed A 1

Committee's Minute 11th March 18 59Character assigned Rest J. L. P.

Certificate (if required)

No. ³⁵⁷ Survey held at London Date 4th March 185 9
 on the Barque Bride Master Liddle
 Tonnage 432 Built at Sunderland When built 1831
 By whom built _____ Owners Temperleys &
 Port belonging to London Destined Voyage London to Cape G. H.
 If Surveyed Afloat or in Dry Dock Princes Dock

Last Survey, No. 21340 Port of London Classed 11 A 1
1. 58

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps <u>2</u>
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>5</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>Good where seen</u>	Keelsons _____	Sails <u>3 suits</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>3 B. 1 S. 1 H.</u>
Sheerstrakes _____	Ceiling _____	Cables <u>300 fms</u>
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>Iron</u> When put on <u>1838</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen

This vessel is in good and efficient condition eligible to remain as classed 11 A 1

Committee's Minute 11th March 18 59Character assigned 11 A 1

Certificate (if required).



Lloyd's Register

Foundation

LON640-0465