

22361

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 144 Survey held at London Date April 15/16 1859
on the Brigantine "Neanches" Master Jas Roberts
Tonnage 187 Built at P. E. Island When built 1838
By whom built _____ Owners Jas Roberts
Port belonging to Carmarvon Destined Voyage Coasting
If Surveyed Afloat or in Dry Dock South West India Dock

Recd 16/4/59

Last Survey, No. 144 Port P. E. Island Classed 7 A

REPAIRS She is now supplied with two Bower Anchors, one Stream
and one Kedge ^{Cast in the} 11" 2" 22 - 10" 2" 8 - 4" 0" 0 ^{Cast in the} respectively -
120 Fathom of Inch Chain Cable and 60 Fathom of 1 1/2 -
and 30 Fathom of Stream Chain -
75 Fathom of 6 1/2 Hawser - 75 Fathom of 4 1/2 Warp
and 90 Fathom of 3 1/2 -

Present Condition of the

Decks	Treenails	Windlass and Capstan <u>Winch good</u>
Waterways } <u>Good</u>	Breasthooks and Stenson	Pumps <u>2 good</u>
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats <u>2 good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Keelsons	Sails <u>Am suit</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>2 B. 1 S. 1 K</u>
Sheerstrakes } <u>Good where</u>	Ceiling	Cables <u>120 fath of 1 1/2 & 60 fath 1 1/2</u>
Topsides } <u>seen</u>	Rudder	Hawsers and Warps <u>good & suff</u>
Wales	Copper <u>none</u> When put on	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen
She is now entitled, in my opinion, to be classed
7 A 1.

W. Maymouth

The Amount of Fee.....£ - : 10 : - is received by me,
Special..... / : / : -
Certificate (if required) : 2 : 6

Committee's Minute 19 April 1859
Character assigned 7 A 1