

REPORT of SURVEY for REPAIRS.

22414

No. ⁶⁶ on the 13th Queen of the Wave Survey held at London Date Feb²⁴ & Mar³ 1859
 Master Brown
 Tonnage 454 Built at Andled When built 1852
 By whom built _____ Owners J Avery
 Port belonging to N Shields Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock A Miss Dowson & Mr Bayly and lastly E India

Recd 8. 3. 59

Last Survey, No. 21939 Port London Classed 10 A 1

REPAIRS

Now done Yellow Metal Sheathing stripped off and renewed upon felt. Caulked from keel upwards to Waterway Seam. Six Iron Bolts in Hold Beam knees and Spiketting replaced with Bolts of Yellow Metal.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson } <u>Good when seen</u>	Pumps <u>new</u>
Comings } <u>Good</u>	Transoms, Pointers, and Crutches } <u>Good when seen</u>	Boats } <u>In good order and sufficient when seen</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>d^o when seen</u>	Keelsons } <u>d^o</u>	Sails } <u>when seen</u>
Planksheers } <u>d^o</u>	Clamps and Shelves } <u>d^o</u>	Anchors No. of <u>3, 11, 11</u>
Sheerstrakes } <u>d^o</u>	Ceiling } <u>d^o</u>	Cables
Topsides } <u>d^o</u>	Rudder } <u>d^o</u>	Hawsers and Warps
Wales } <u>d^o</u>	Copper Metal a felt When put on <u>new new</u>	Standing & Running Rigging
Plank (Bottom) and Counter } <u>d^o</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good when tried

This Barque now appears to be in good condition eligible to remain as Classed A 1

The Amount of Fee.....£ : : is received by me,

For fee attending } Special..... 1 : 1 : 0
 to try Caulking }
 Certificate (if required) : : :

J A Martin

Committee's Minute 13th May 1859

Character assigned 10 A 1

record Wm
Miss J W Smith

