

## ANNUAL SURVEYS.

22420

No. 360 on the B<sup>th</sup> "Shallett" Survey held at London Date 21<sup>st</sup> April 1859  
 Master G. Peart  
 Tonnage 427 Built at Blyth When built 1853  
 By whom built \_\_\_\_\_ Owners Dale & Co  
 Port belonging to Shields Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Bridge dry dock

Last Survey, No. 21574 Port of London Classed 183 8 Δ  
 2, 58

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>where</u>	Timbers of the Frame	} <u>where</u>	Masts, Yards, &c.	} <u>Suffr</u>
Lower Deck Beams & Fastenings		Keelsons <u>where examined</u>		Sails	
Planksheers		Clamps and Shelves <u>clear of Ballast</u>		Anchors No. of <u>2 B. 1 S &amp; 1 1/2</u>	
Sheerstrakes	} <u>seen</u>	Ceiling	} <u>do</u>	Cables	} <u>Good</u>
Topsides		Rudder		Hawsers and Warps	
Wales		<u>Yellow metal on feet</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>not seen</u>	Copper	<u>When put on 1838</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Docked to examine bottom and repair keel metal, a  
bower Anchor to be supplied at Shields to make good deficiency she is at  
present in good condition and eligible to continue as classed 8 A 1 when  
supplied with the 3<sup>rd</sup> Bower Anchor.

Committee's Minute 13<sup>th</sup> May 1859Character assigned 8 A 1

Will<sup>m</sup> L. Davey  
J. C. Martin

Surgeon at Shields Letter 13. 5. 59 Certificate (if required)

No. 307 on the B<sup>th</sup> "Sebastian" Survey held at London Date 26<sup>th</sup> April 1859  
 Master N. Begg  
 Tonnage 426 Built at Tunderland When built 1853  
 By whom built \_\_\_\_\_ Owners Voyce & Co  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Nelson dry dock

Last Survey, No. 21489 Port of London Classed 7 A 1  
 57

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <u>where</u>	Timbers of the Frame	} <u>where</u>	Masts, Yards, &c.	} <u>and</u>
Lower Deck Beams & Fastenings		Keelsons		Sails	
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes	} <u>seen</u>	Ceiling	} <u>seen</u>	Cables	} <u>Suffr</u>
Topsides		Rudder		Hawsers and Warps	
Wales		<u>Yellow metal on feet</u>		Standing & Running Rigging	
Plank (Bottom) and Counter	<u>not seen</u>	Copper	<u>When put on 1857</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Docked to examine bottom, she is in good condition  
and eligible to continue as classed 7 A 1

Committee's Minute 13<sup>th</sup> May 1859Character assigned 7 A 1

Will<sup>m</sup> L. Davey  
J. C. Martin

Certificate (if required).

Lloyd's Register  
 Foundation  
 LON 641-0101