

ANNUAL SURVEYS.

22434

No. ¹⁶⁰ on the *Ship "Violet"* Survey held at *London* Date *Apr 1st 1859*
 Tonnage *510* Built at *Sunderland* Master *C. P. P. P.*
 By whom built *C. P. P. P.* Owners *C. P. P. P.*
 Port belonging to *London* Destined Voyage *Carter's Dry Dock*
 If Surveyed Afloat or in Dry Dock *Carter's Dry Dock*

Last Survey, No. *21030* Port of *London* Classed *13 A 1.*

The present Condition of the

Decks *good*
 Waterways *"*
 Comings *"*
 Upper Deck Beams & Fastenings *good*
 Lower Deck Beams & Fastenings *where seen*
 Planksheers *"*
 Sheerstrakes *"*
 Topsides *"*
 Wales *"*
 Plank (Bottom) and Counter *"*

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame *good*
 Keelsons *where seen*
 Clamps and Shelves *seen*
 Ceiling
 Rudder
 Copper *y. m.* When put on *1858*

Windlass and Capstan *good*
 Pumps *"*
 Boats *good and sufficient*
 Masts, Yards, &c.
 Sails
 Anchors No. of
 Cables
 Hawseers and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good where seen.*

This vessel appears in good condition, and in my opinion eligible to remain as Classed 13 A 1.

Committee's Minute

Character assigned

17th May 1859
13 A 1

J. P. P. P.

Certificate (if required)

No. ⁵⁷² on the *Ship "Collingwood"* Survey held at *London* Date *Apr 11th 1859*
 Tonnage *680* Built at *Sunderland* Master *J. Ramsey*
 By whom built *Middle Dock Co.* Owners *Middle Dock Co.*
 Port belonging to *Newcastle* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Carter's Dry Dock and E. D. Dock*

Last Survey, No. *7126* Port of *Newcastle* Classed *Res 138 for 7 1/2*

The present Condition of the

Decks *good*
 Waterways *"*
 Comings *"*
 Upper Deck Beams & Fastenings *good*
 Lower Deck Beams & Fastenings *where seen*
 Planksheers *"*
 Sheerstrakes *"*
 Topsides *"*
 Wales *"*
 Plank (Bottom) and Counter *"*

Treenails
 Breasthooks and Stemson
 Transoms, Pointers, and Crutches
 Timbers of the Frame *good*
 Keelsons *where seen*
 Clamps and Shelves *seen*
 Ceiling
 Rudder
 Copper *y. m.* When put on *1858*

Windlass and Capstan *good*
 Pumps *"*
 Boats *good and sufficient*
 Masts, Yards, &c.
 Sails
 Anchors No. of
 Cables
 Hawseers and Warps
 Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good where seen.*

Now done. 4, roughness on the port side amidships and rail in way of the same being damaged have been renewed, side caulked in way of d. and metal patched. She now appears in a condition

Committee's Minute

Character assigned

17th May 1859
Res 138

J. P. P. P.
 Certificate (if required).