

# ANNUAL SURVEYS.

22514

No. <sup>257</sup> Survey held at London Date Feb 28<sup>th</sup> 1859  
 on the Ship Blackwall Master W<sup>m</sup> Stewart  
 Tonnage 710 Built at London When built 1830  
 By whom built 1 Owners P. Green  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Mr<sup>s</sup> Green's Dry Dock

Recd 8/4/59  
 Sub

Last Survey, No. 21707 Port of London Classed 13A.1  
 58

The present Condition of the

Decks	} <u>Good</u>	Treenails	}	Windlass and Capstan
Waterways		Breasthooks and Stenson		Pumps
Comings	} <u>Good where seen</u>	Transoms, Pointers, and Crutches	}	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} <u>Good where seen</u>	Keelsons	}	Sails
Planksheers		Clamps and Shelves		Anchors No. of
Sheerstrakes	} <u>Good where seen</u>	Ceiling	}	Cables
Topsides		Rudder		Hawsers and Warps
Wales	} <u>Good where seen</u>	<u>Yellow Metal</u>	}	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>		<u>Copper on Telt</u> When put on <u>now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where tested

She has now had her bottom Caulked and is sheathed with Yellow Metal on Telt. And is fit in my opinion to remain as classed 13A.1.

P. Weymouth

Committee's Minute 7<sup>th</sup> July 1859

Character assigned

13A.1

recd W. M. L. R.

Certificate (if required)

No. <sup>400</sup> Survey held at London Date March 22<sup>nd</sup> 1859  
 on the Ship "Lyburnia" Master F. Coote  
 Tonnage 1027 Built at Glasgow When built 1837  
 By whom built 953 Owners Messrs James Bro'  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

W. M. L. R.

Last Survey, No. 1370 Port of Glasgow Classed 14A.1  
 57

The present Condition of the

Decks	} <u>Good</u>	Treenails	}	Windlass and Capstan
Waterways		Breasthooks and Stenson		Pumps
Comings	} <u>Good where seen</u>	Transoms, Pointers, and Crutches	}	Boats
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.
Lower Deck Beams & Fastenings	} <u>Good where seen</u>	Keelsons	}	Sails
Planksheers		Clamps and Shelves		Anchors No. of
Sheerstrakes	} <u>Caulked</u>	Ceiling	}	Cables
Topsides		Rudder		Hawsers and Warps
Wales	} <u>Good where seen</u>	<u>Yellow Metal</u>	}	Standing & Running Rigging
Plank (Bottom) and Counter <u>Caulked</u>		<u>Copper on Telt</u> When put on <u>now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where tested

She is fit in my opinion to remain as classed 13A.1. Has been caulked from keel to gunwale and her bottom is sheathed with Yellow Metal on Telt.

P. Weymouth

Committee's Minute 8<sup>th</sup> July 1859

Character assigned

14A.1

recd W. M. L. R.

Certificate (if required)