

22533

REPORT of SURVEY for REPAIRS.

and Re Entry

No. 171 Survey held at London Date 1st & 2nd July 1859
 on the 13th "Bermondsey" Master A. Abbott
 Tonnage 445 Built at Whisby When built 1841
 By whom built 506 Owners Wilson &
 Port belonging to London Destined Voyage Cape Good Hope
 If Surveyed Afloat or in Dry Dock Pontoon Victoria docks

Last Survey, No. 21301 Port London Classed 10 *F. 1 SS 54
C 3 7 Claps on water

REPAIRS

One piece of Rider Keelson of American Elm. 2 planks of deck of Yellow Pine and two pieces of inside bilge planks

wood sheathed from keel to Wales and remetalled on felt at Singapore in July 1858 and the bottom then recaulked the bills of which have been produced and examined

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps	
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>In good</u>
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Keelsons	<u>where</u>	Sails	<u>order and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling <u>where seen clear of ballast</u>		Cables	
Topsides	<u>seen</u>	Rudder	<u>seen</u>	Hawsers and Warps	<u>suffr</u>
Wales <u>part sheathed 1858</u>		Yellow Metal on felt		Standing & Running Rigging	
Plank (Bottom) and Counter <u>not seen</u>		Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

This Vessel appears at present in good condition fit for the safe conveyance of dry & perishable cargoes and may therefore be ventred and classed *F. 1 SS 54

The Amount of Fee.....£ 1 : : is received by me,

Special..... : : W. L. Davy

Certificate (if required) : 5 : -

Committee's Minute 21 July 1859Character assigned F. 1 asterisk
record repairs

© 2019

Lloyd's Register
Foundation

LON 641-0209