

ANNUAL SURVEYS.

22581

Recd 10.8.59

No. 24 on the S. "Jason" Survey held at London Date 29th July 1859
 Tonnage 877.65 Built at Aberdeen When built 1838
 By whom built W. Moore & Co Owners Mr Adamson
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 1829 Port of Aberdeen Classed 10 A1
 58

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	<u>Yellow metal on</u> <u>seen</u>	} <u>seen</u>	Standing & Running Rigging	} <u>supp</u>
Plank (Bottom) and Counter		<u>Copper</u> <u>ft</u> <u>sheet</u>		When put on <u>July 1859</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where tested
Now stripped through to metal, tested caulking in various
parts and found it satisfactory. Resheathed with Yellow metal on part of
part paper and she is now in good condition and eligible to remain
as classed 10 A1

Committee's Minute 12th August 1859 Will^m B. Davey

Character assigned 10 A1 record W B D Certificate (if required)

No. 162 on the S. "Himrod" Survey held at London Date 30th July 1859
 Tonnage 1022 Built at Scarboro' When built 1833
 By whom built Widdalls Owners Widdalls
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Mr Green's dry dock

Last Survey, No. 21926 Port of London Classed 13 A1
 58

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>and</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	<u>Yellow metal</u> <u>seen</u>	} <u>seen</u>	Standing & Running Rigging	} <u>supp</u>
Plank (Bottom) and Counter		<u>Copper</u>		When put on <u>July 1859</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where tested
Now stripped through to metal, tested the caulking in
various places and found it satisfactory. Now ends & bolts now resheathed
Resheathed with Yellow metal on paper she is in good condition and
eligible to continue as classed 13 A1

Committee's Minute 12th August 1859 Will^m B. Davey

Character assigned 13 A1 record W B D Certificate (if required)