

22753

# REPORT of SURVEY for REPAIRS.

No. 869 Survey held at Londonderry Date 2<sup>nd</sup> Dec 1859  
on the Ship Symmetry Master W Rogers  
Tonnage 382 Built at Seaside When built 1823  
By whom built \_\_\_\_\_ Owners Tindale  
Port belonging to Londonderry Destined Voyage Londonderry  
If Surveyed Afloat or in Dry Dock Millvale dry dock

Last Survey, No. 21046 Port Londonderry Classed A.S. 1  
REPAIRS Rest 40-7 Gro C 2 S S 34. 5-8.

The Yellow metal sheathing stripped off the bottom  
the vessel could be seen from keel over all  
two planks of ceiling in hold on the port side (one  
aft & one forward) renewed of better oak. other parts of the  
ceiling forward and aft, also the upper deck clamps,  
piced and repaired.

## Present Condition of the

Decks <u>Good</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>Fair</u>	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers <u>Good where seen</u>	Clamps and Shelves <u>repaired</u>	Anchors No. of <u>3 B. 1 S. 2 M.</u>
Sheerstrakes <u>doublets</u>	Ceiling _____	Cables _____
Topsides _____	Rudder <u>Good</u>	Hawsers and Warps _____
Wales _____	Copper <u>When put on</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion, \_\_\_\_\_ Caulking of Bottom, Deck, & Waterways. Good where tried

This vessel is at present in good and efficient  
condition fit for the safe conveyance of dry and perishable  
cargoes to and from all parts of the world and eligible  
to remain as classed A.S. 1

The Amount of Fee.....£ : : is received by me,  
Special..... 1 : 1 :  
Certificate (if required) : 5 : -

Committee's Minute 15<sup>th</sup> November 1859  
Character assigned A.S. 1 asterisk

W. J. R. Rumbold  
W. W. W. W.

Expenses W. M. A. R.