

REPORT of SURVEY for REPAIRS.

22896

Recd. 27/1/60

No. 219 Survey held at London Date 14th to 28th Jan^r 1860
 On the S. "Atalanta" Master R. Spratley
 Tonnage 930 Built at New Brunswick When built 1855
 By whom built _____ Owners Wilson &
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Some dry dock

Last Survey, No. 21513 Port London Classed YA1
 58

REPAIRS

Gellows metal stripped off likewise wood sheathing on lower part of wales and upper courses of bottom. hawse boxes and hawse pipes removed, worn part of fore piece of keel cut out and piece $1\frac{1}{2}$ in thick, the ship hump in shores recaulked from keel to Waterway beam, lower courses of wales and upper courses of bottom sheathed with wood over feet and fastened with composition nails, hawse pipes rebedded on lead & bolted. new fore & main masts & fore top mast bottom unmetalled on feet

Present Condition of the

Decks		Treenails		with P.P.	
Waterways		Breasthooks and Stemson	where	Windlass and Capstan	Good
Comings		Transoms, Pointers, and Crutches	seen	Pumps	2 of Sea do
Upper Deck Beams & Fastenings	Good	Timbers of the Frame		Boats	5 No do
Lower Deck Beams & Fastenings		Keelsons	Good	Masts, Yards, &c.	part new do
Planksheers		Clamps and Shelves	where seen clear of ballast	Sails	2 sets do
Sheerstrakes	where	Ceiling		Anchors	No. of 3 B. 1 S & 1 K
Topsides		Rudder	d.	Cables	complete
Wales	seen	Copper	1 lb on feet When put on Jan 1860	Hawsers and Warps	4 No Supr
Plank (Bottom) and Counter				Standing & Running Rigging	Good

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

This vessel is now in good condition and eligible in our opinion to continue as classed YA1

The Amount of Fee.....£ _____ is received by me,

Special Allowance 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 3rd February 1860

Character assigned YA1

Wm L. Davy

A. Martin



© 2019 Lloyd's Register Foundation

LON 642-0115