

22924

REPORT of SURVEY for REPAIRS.

No. ⁸⁸² on the S. "Monarch" Survey held at London Date 21st to 28th July 1859
Master C. Viershnie
Tonnage 1350 Built at London When built 1844
By whom built 1415 Owners R Green
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Mr Green's dry dock

Last Survey, No. 21157 Port London Classed 12 A1
Cont^d 56 - 4 yrs

REPAIRS

Yellow Metal stripped off, recaulked from keel to gunwale and the bottom resheathed with Yellow Metal over felt
Midship piece of beam abaft Mizzen Mast of spar deck new of Pitch Pine, hammock berthing of waist removed and replaced with Bulwark Stanchions, Rails &c - new Mizzen Mast -
new Caulking tested and found satisfactory.

Present Condition of the

| | | | | | |
|-------------------------------|----------------|---|---------------|----------------------------|----------------|
| Decks | } <u>Good</u> | Treenails | } <u>Good</u> | Windlass and Capstan | } <u>Good</u> |
| Waterways | | Breasthooks and Stenson | | Pumps | |
| Comings | | Transoms, Pointers, and Crutches | | Boats | |
| Upper Deck Beams & Fastenings | | Timbers of the Frame | | Masts, Yards, &c. | |
| Lower Deck Beams & Fastenings | } <u>where</u> | Keelsons | } <u>seen</u> | Sails | } <u>and</u> |
| Planksheers | | Clamps and Shelves | | Anchors No. of | |
| Sheerstrakes | } <u>seen</u> | Ceiling ^{where seen clear} of Ballast &c | } <u>good</u> | Cables | } <u>Suffr</u> |
| Topsides | | Budder | | Hawsers and Warps | |
| Wales | | Green Metal on feet | | Standing & Running Rigging | |
| Plank (Bottom) and Counter | | Copper When put on <u>July 1859</u> | | | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested -

This vessel appears in good condition and may continue as Classed A

Will: C. Davy

The Amount of Fee.....£..... is received by me,

Special..... } 1: 1:- }
extra attend ance
Certificate (if required)

Committee's Minute 14th February 1856

Character assigned Cont 4-1

second Y.M.D.