

REPORT of SURVEY for REPAIRS.

23037

No. 571 on the Bk "Clive" Survey held at London Date 23 Feb to 7 Mar 1860
 Master A. Shaw
 Tonnage 591 Built at Newcastle When built 1834
 By whom built J & W Smith Owners J & W Smith
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Rep^d Nyeau's dry dock

Recd 24. 3. 60

Last Survey, No. 22276 Port London Classed 13 A1
 1. 59

REPAIRS

Yellow metal shipped off, recanted from keel to gunwale and remetalled on paper.

Through damage by collision on the Port side 9 complete timbers of English Oak, 2 planks of the strake of English Oak new Plank sheer from fore side of main chain forward of East India Stalk also new main bulwark Rails & sheathing in the same space

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	Good	Transoms, Pointers, and Crutches	Good	Boats	Good
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	where	Keelsons	where	Sails	and
Plank sheers		Clamps and Shells		Anchors No. of	
Sheerstrakes		Ceiling	seen	Cables	
Topsides	seen	Rudder		Hawsers and Warps	supp
Wales		Copper <u>Yk on paper</u> When put on <u>Mar/60</u>		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is now in good condition & eligible to continue as classed 13 A1

Will^m C. Dancy

The Amount of Fee.....£ : : is received by me,

Special att^{ch} } 1 : 1 : -
 attendance
 Certificate (if required) : : -

Committee's Minute 10th April 1860

Character assigned 13 A1

record
 A.D.



© 2019

Lloyd's Register Foundation

LON 642-0272