

REPORT of SURVEY for REPAIRS.

23082

No. ³⁸⁴ on the S. Wynaund Survey held at London Date Feb^r 28th 1860
 Master Reid
 Tonnage 596 Built at London When built 1854
 By whom built _____ Owners A. G. Robinson
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Simhouse dry dock

Recd 14.4.60

Last Survey, No. 22357 Port London Classed 13A1
 4,39

REPAIRS

Now done: yellow metal stripped ship recaulked from planksheers to keel and the yellow metal renewed upon felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>7 1/2 YNE</u> When put on <u>now</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tried

This vessel appears in good condition and is eligible in our opinion to remain as classed
 13A1

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 17th April 1860

Character assigned 13A1

record Mr. Reid



© 2019

Lloyd's Register Foundation

LON 642-0299