

ANNUAL SURVEYS.

23097

No. 400 on the Pt "Prince Arthur" Survey held at London Date 20th to 27th Mar 1860
 Tonnage 411 Built at Northfleet Master Wishart
 By whom built 436 Owners Hudson Bay Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mr Green's dry dock

Recd 17/4/60
C.R.

Last Survey, No. 21709 Port of London Classed 13A1
 58

The present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>In good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>order</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>seen</u>	Copper <u>none</u> When put on _____	} <u>seen</u>	Standing & Running Rigging	} <u>Suffr</u>
Plank (Bottom) and Counter <u>fixed 54</u>					

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good where tested
Keel in shaves recanted from keel over all; 2 species of
deck was renewed and one short piece of Port planksheer she is now
in good condition and eligible to continue as classed 13A1
Will B. Davey

Committee's Minute 20th April 1860
 Character assigned 13A1

Certificate (if required)

No. 105 on the 13th Beetham Survey held at Liverpool Date 2nd to 11th March 1860
 Tonnage 239 Built at Liverpool Master _____
 By whom built _____ Owners W Wilson
 Port belonging to Liverpool Destined Voyage London to River Plate
 If Surveyed Afloat or in Dry Dock Liverpool dry dock

Recd 17/4/60
C.R.

Last Survey, No. 15885 Port of Liverpool Classed 10A1
 Rev-53. 7-7

The present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good where seen</u>	Windlass and Capstan	} <u>Good</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} <u>where seen</u>	Keelsons	} <u>not seen for lumber</u>	Sails	} <u>And</u>
Planksheers		Clamps and Shelves		Anchors No. of	
Sheerstrakes		Ceiling		Cables	
Topsides		Rudder		Hawsers and Warps	
Wales	} <u>Good</u>	Copper <u>felt</u> When put on <u>1857</u>	} <u>seen</u>	Standing & Running Rigging	} <u>Suffr</u>
Plank (Bottom) and Counter					

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen
This vessel appears in good and efficient condition
eligible to remain as classed A1

Committee's Minute 20th April 1860
 Character assigned Rest 7A1

W. Wilson

Certificate (if required).